




Holes and Pockets



Create the stock for the part


- Select AUTOMATIC STOCK
- Select a SHAPE of [BOX]
- For this activity we will leave all the stock box offsets at ZERO




Evaluate and redefine the part reference zero PRZ or CPL

- For this example, the PRZ should not need to be reset. It has been created in Autodesk Inventor with the correct PRZ as we would like to assign it.

Nothing needs to be done at this step.



Use the feature finder to allow EdgeCAM to evaluate the 3D CAD model in order to break the model into manufacturable features




Hole Options

Find Vertical
 CAD Link Information
 Match to Template
 Group Similar Holes
 Maximum Diameter = The largest tool you have to be able to drill with (Example = 0.25)

Mill Options

2D Pocket
 2D Boss

All features found will now be displayed on the features tab




Leave DESIGN mode and enter MANUFACTURE mode

DISCIPLINE – [Mill]

MACHINE TOOL – Choose the correct POST for your machine [intelitek.mcp]

INITIAL CPL – Ensure the CPL is [Top]




Switch from the SEQUENCE tab back to the FEATURES tab

-Select the grouped BLIND HOLES from the features list.

Note: As you hover over the features, they should highlight the corresponding feature on the 3D model.

Right click on the second BLIND HOLES and select HOLE OPERATION for MILLING Operation from the list



GENERAL

- CLEARANCE – [0.5]
- LEVEL – [0]
- OFFSET – [0]
- TERMINATION [BLIND]

CENTER/SPOT

- Strategy – [None]

PREPERATION



- Strategy – [No Preparation]

ROUGHING

- STRATEGY [Drill]
- DEPTH [0.0]



TOOLING

- 1ST Choose the FIND box
- Choose NO to creating a new tool (we need to use an end mill to create a blind pocket with a flat drill point, not a drill (spiral tool))




-2nd Select the END MILL filter to expose end mill options that will fit the hole selected


-3rd Select the 1/4 End Mill



FINISHING

-STRATEGY [No Finishing]






Simulate the machining process

Once the simulator opens, Select PLAY

Ensure the simulator produce the results desired

Close the simulator to return to EdgeCAM



Select boundary entities (Finish for none)

Select the roughing operation from the top toolbar. This operation will be used to rough BOTH counterbores at the same time




Select both counterbores to be machined

At this time we do not need to define any boundaries for this operation. Select either select the check mark in the top right corner, select enter on the keyboard, or right click to select DONE



GENERAL

-MILL TYPE – Select [CLIMB]



-% STEPOVER – [50%]

-OFFSET – [0] (Used to leave material on all axis (X, Y and Z). A finishing operation can then be used to remove the offset material

-Z OFFSET – [0] (Used to leave material on only the Z Plane of the surface defined. Also used along with the offset to override the Z axis if a quantity is left from the Offset line

-TOLERANCE – [0.001 to 0.005]

TOOLING

-USE CURRENT TOOL

DEPTH


-CLEARANCE – [0.25] - Retract point above the PRZ

-LEVEL – [0] – Measured from the top of the feature selected

-DEPTH – [0] - Measured from the bottom of the feature selected

-CUT INCREMENT – [0.125] - determine a safe number for the tool you are using to go from the level to the depth. If the Cut Increment is smaller than depth, the facing operation will produce multiple passes to go from the level to the depth.

For prototyping material, use approximately 1/2 to 1/3 the bit diameter as the cut increment




Repeat the previous steps for both the holes of the counterbores




Simulate the machining process

Once the simulator opens, Select PLAY



Ensure the simulator produce the results desired



Select the COMPARE tool – this option will compare the original 3D model and the results of the simulated operations. At this time since we raised the stock above the 3D model, set the facing operation to only cut the amount raised from the 3D model, the compare should show as all green

GREEN – Simulation and CAD model areas that Match

BLUE – Areas not removed or remaining from the stock to produce the 3D model

	<p>RED – Areas removed from the stock that have cut into the 3D model</p> <p>Close the simulator to return to EdgeCAM</p>
	<p><i>*Note: If EdgeCAM is running in HOME WORK mode, producing the NC code is not available</i></p> <p>Select NC tool from the tool bar to produce the NC code using the POST Processor selected earlier</p>